

(Provincial)

665552

Serial No. Y

10-09 2024

Received from ਮੁਖੀ, 3 ਹਵਾ ਮੁਖੀ
ਮਾਡ, ਮਾਡੀ ਮਾਡੀ, ਮਾਡੀ

with letter No. dated 20

the sum of Rupees 10000 (ਦਸ ਹਜ਼ਾਰ ਰੁਪਏ)

in Cash/by Cheque on account of

in payment of ਮੁਖੀ, ਮਾਡੀ
ਮਾਡੀ ਮਾਡੀ ਮਾਡੀ ਮਾਡੀ

Rs. Signature

Sub. Divisional Engineer
Const. Sub-Divn. PWD B&F
Lehragaga

ਵੱਲੋਂ,

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ. ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਲਹਿਰਾਗਾਗਾ।

ਵੱਲੋਂ,

ਚੇਅਰਮੈਨ,
ਦ ਰੂਟਸ ਮਿਲੇਨੀਅਮ ਸਕੂਲ,
ਰੈਸਟਹਾਉਸ ਦੇ ਪਿੱਛੇ, ਖਨੌਰੀ ਮੰਡੀ।

ਨੰ. 245

ਮਿਤੀ. 10-09-2024

ਵਿਸ਼ਾ:- ਬਿਲਡਿੰਗ ਸੁਰੱਖਿਆ ਸਰਟੀਫਿਕੇਟ ਲੈਣ ਸਬੰਧੀ। (The Roots Millennium School, Khanauri Mandi)

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਆਪ ਦੀ ਮੰਗ ਅਨੁਸਾਰ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਸਬੰਧੀ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਨਿਰਧਾਰਿਤ ਪ੍ਰੋਫਾਰਮੇ ਤੇ ਆਪ ਨੂੰ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ। ਲੋੜੀਂਦੀ ਫੀਸ ਜੀ.ਆਰ. ਨੰ. 665552 ਮਿਤੀ 10.09.2024 ਰਾਹੀਂ ਬਾਬਾਤ ਰਕਮ 10,000/- ਰੁਪਏ ਪ੍ਰਾਪਤ ਕਰ ਲਈ ਗਈ ਹੈ। ਆਪ ਦੇ ਫਾਇਰ ਸੇਫਟੀ ਦੇ ਸਰਟੀਫਿਕੇਟ ਦੀ ਮਿਆਦ ਨਵੰਬਰ-2024 ਤੱਕ ਦੀ ਹੈ, ਇਸ ਲਈ ਨਵੰਬਰ ਵਿੱਚ ਫਾਇਰ ਸੇਫਟੀ ਦਾ ਸਰਟੀਫਿਕੇਟ ਰੀਨਿਊ ਕਰਵਾਇਆ ਜਾਵੇ, ਨਾ ਕਰਵਾਉਣ ਦੀ ਸੂਰਤ ਵਿੱਚ ਇਸ ਦਫਤਰ ਵੱਲੋਂ ਜਾਰੀ ਕੀਤਾ ਗਿਆ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਰੱਦ ਸਮਝਿਆ ਜਾਵੇਗਾ।

ਨੱਥੀ/ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ।



ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ, ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਲਹਿਰਾਗਾਗਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ.

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਤਕ ਮੰਡਲ, ਲੋ.ਨਿ.ਵਿ., ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਯਕਤੂਰ ਜੀ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ. 3321 ਮਿਤੀ 30.07.2024 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।




ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ, ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਲਹਿਰਾਗਾਗਾ।

Building Safety Report

Name of College:- **The Roots Millennium School.**

I have visited the above mentioned school building along with **Sh Manish Kumar JE** on **06-09-2024** and have visually inspected. It seems visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications. Test Reports of Material used Quality Control reports and certificate from Engineer in Charge for construction are not available.
- b) In case of any addition, alteration or expansions and modification to this building are done; certificate may be re-obtained after completion from undersigned.
- c) In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- e) A separate certificate regard Electrical Works should be obtained from the competent authority.
- f) The owner of the building/ Management is fully responsible regarding safety of building from all angels in spite of this report.
- g) The covered area of the building is **18622 Sq.ft.**
- h) This Report is not valid for legal purpose.
- i) This building visually seems safe to occupy for the normal use up to: **31-03-2025**
- j) The Building Certificate should not be considered as NOC for Road Access which will be taken separately by School as per Government policy No. 05/13/2018-3BR3/1294287/3 dated 10-08-2018.


Sub Divisional Engineer,
Const. Sub Division, PWD B&R,
Lehragaga.


JE